


Date: Tuesday, 14/10/2008 9:50:39 AM  
 User: Linda Lacelle

## Process Sheet

<b>Customer</b> :	CU-DAR001 Dart Helicopters Services	<b>Drawing Name</b> :	HARNESS ASSEMBLY	
<b>Job Number</b> :	42553	<b>Part Number</b> :	D412702113B	
<b>Estimate Number</b> :	12860	<b>Drawing Number</b> :	ICA D412-702 P79 R3	
<b>P.O. Number</b> :		<b>Project Number</b> :	N/A	
<b>This Issue</b> :	14/10/2008	<b>S.O. No.</b> :		
<b>Prsht Rev.</b> :	NC	<b>Drawing Revision</b> :	3	
<b>First Issue</b> :	//	<b>Type</b> :	SMALL /MED FAB	
<b>Previous Run</b> :	42550	<b>Material</b> :		
<b>Written By</b> :			<b>Due Date</b> :	15/10/2008
<b>Checked &amp; Approved By</b> :			<b>Qty:</b>	1 Um: Each
<b>Comment</b> :	: est rev A 07.05.11 new issue EC Est Rev:B Removed Decal D3569 07-07-06 JLM			

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	D35702	Bracket
-----	--------	---------




**Comment:** Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

BRACKET

batch: \_\_\_\_\_

32345

 08/10/14 (X)

2.0	D3579048	Shoulder Harness
-----	----------	------------------




**Comment:** Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

SHOULDER HARNESS RH

batch: \_\_\_\_\_

33103

 08/10/14 (X)

3.0	MS24694S50	Screw
-----	------------	-------




**Comment:** Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)

Screw

batch: \_\_\_\_\_

M108673

 08/10/14 (X)

4.0	AN960JD10L	Washer
-----	------------	--------




**Comment:** Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)

Washer

batch: \_\_\_\_\_

M105793

 08/10/14 (X)

5.0	MS21042L3	Nut
-----	-----------	-----




**Comment:** Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)

Nut

batch: \_\_\_\_\_

M10870

 08/10/14 (X)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

Date: Tuesday, 14/10/2008 9:50:39 AM  
User: Linda Lacelle

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: HARNESS ASSEMBLY

Job Number: 42553

Part Number: D412702113B

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Assemble as per dwg ICA D412-702 p.79

7.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

8.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify with P/N & CHG# and pack for shipping as per PPP D412-702-113B CHG001

Location: \_\_\_\_\_

PPP Rev: \_\_\_\_\_

PP042543

9.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



6081015


W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_


Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries



**DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-117A AND  
D412-702-101B/-103B/-105B/-107B/-109B/-115B/-117B HARNESS ASSEMBLIES**  
(BELTS, K6.2 CLIP AND D3569-1/-2/-3 DECAL NOT SHOWN)



**DETAIL 'L' D412-702-111A/-111B/-113A/-113B HARNESS ASSEMBLIES**  
(BELTS AND D3569-1/-2/-3 DECALS NOT SHOWN)

*W/0 42553*

• COPYRIGHT © 2004 BY DART AEROSPACE LTD. •  
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR  
COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries